50IU-FM03 Installation Guide



Α	50IU-FM03 Insert unit
В	Recommend table top thickness = T T = 19mm (3/4") T = 25mm (1") T = 38mm (1-1/2") T = 50mm (2")

1	Machine screw with spring & flat washer	
а	M4 × 12 for T = 19mm $(3/4")$	5
b	M4 × 18 for T = 25mm (1")	5
С	$M4 \times 31$ for T = 38mm (1-1/2")	5
d	M4 × 44 for T = 50mm (2")	5

Table top hole cut dimensions



SECTION A-A